




# UN THREAD MILLS

## SINGLE PROFILE (SPTM) - SOLID CARBIDE



- Solid carbide provides maximum tool rigidity
- Long reach tools are available from stock
- Cuts UNC, UNF, UNEF, and UNS threads
- Cuts UNJ threads (internal only)

Min ID THREAD*	"A" TOOL DIA.	"B" LENGTH OF CUT	"C" NECK DIA.	"Q" LENGTH	"S" SHANK DIA.	OAL	RECOM- MENDED TPI	FLUTES	ORDER #	
									UNCOATED	ALTiN+
									INTERNAL OR EXTERNAL THREADS	
1/4	0.182	0.400	0.104	0.025	0.250	2.50	18 to 56	4	SPTM182	SPTM182A
1/4	0.182	0.530	0.104	0.025	0.250	2.50	18 to 56	4	SPTM182ML	SPTM182MLA
1/4	0.182	0.650	0.104	0.025	0.250	2.50	18 to 56	4	SPTM182L	SPTM182LA
5/16	0.240	0.500	0.153	0.028	0.250	2.50	16 to 48	4	SPTM240	SPTM240A
5/16	0.240	0.800	0.153	0.028	0.250	2.50	16 to 48	4	SPTM240L	SPTM240LA
3/8	0.290	0.600	0.192	0.031	0.375	3.00	14 to 40	4	SPTM290	SPTM290A
3/8	0.290	1.000	0.192	0.031	0.375	3.00	14 to 40	4	SPTM290L	SPTM290LA
1/2	0.372	0.750	0.240	0.041	0.375	3.00	12 to 32	4	SPTM372	SPTM372A
1/2	0.372	1.200	0.240	0.041	0.375	3.00	12 to 32	4	SPTM372L	SPTM372LA
5/8	0.488	0.850	0.340	0.046	0.500	3.50	11 to 32	5	SPTM488	SPTM488A
5/8	0.488	1.350	0.340	0.046	0.500	3.50	11 to 32	5	SPTM488L	SPTM488LA
3/4	0.595	1.250	0.430	0.051	0.625	4.00	10 to 32	6	SPTM595	SPTM595A
3/4	0.595	2.000	0.430	0.051	0.625	4.00	10 to 32	6	SPTM595L	SPTM595LA
7/8	0.695	1.500	0.490	0.063	0.750	5.00	8 to 24	6	SPTM695	SPTM695A
7/8	0.695	2.500	0.490	0.063	0.750	5.00	8 to 24	6	SPTM695L	SPTM695LA
1¼	0.745	1.500	0.400	0.107	0.750	5.00	4 to 8	6	SPTM745	SPTM745A
1¼	0.745	2.500	0.400	0.107	0.750	5.00	4 to 8	6	SPTM745L	SPTM745LA

TPI = Threads Per Inch

**\*Single profile thread mills can cut any larger size internal thread within the recommended TPI**

åãäåäåÄÄ, Ë^, { æ ç [ | • È { ÅÅ / Å È € Æ Í È Ì | Å Å Å Å | • O } ^, { æ ç [ | • È {



# THREAD MILL FEED AND SPEED CHART

MATERIAL	HB/Rc	SPEED SFM* UNCOATED	SPEED SFM ALTiN+	FEED ( INCHES PER TOOTH)					
				TOOL DIAMETER					
				.032 - .056	.059 - .090	.100 - .190	.200 - .350	.370 - .595	.600+
CAST IRON	160 HB	100-220	200-425	.0004-.001	.0004-.0008	.0004-.0014	.0004-.002	.0004-.0035	.0004-.006
CARBON STEEL	18 Rc	100-200	190-425	.0003-.001	.0003-.0008	.0003-.0014	.0003-.002	.0003-.005	.0003-.006
ALLOY STEEL	20 Rc	80-200	200-375	.0003-.001 2 Passes	.0003-.0008 3 Passes	.0003-.0014	.0003-.0024	.0003-.005	.0003-.006
TOOL STEEL	20 Rc	80-175	175-250	.0003-.0004 2 Passes	.0003-0.0005 3 Passes	.0003-.0005	.0003-.0009	.0003-.0026	.0003-.004
300 STAINLESS STEEL	150 HB	90-120	120-255	.0003-.0005 2 Passes	.0003-0.0006 3 Passes	.0003-.0007	.0003-.002	.0003-.0035	.0003-.0045
400 STAINLESS STEEL	195 HB	90-150	140-375	.0003-.0005 2 Passes	.0003-.0006 3 Passes	.0003-.0007	.0003-.002	.0003-.0026	.0003-.0045
HIGH TEMP ALLOY (Ni & Co BASE)	20 Rc	50-125	100-125	.0003-.0004 3 Passes	.0003-.00045 3 Passes	.0003-.0005 2 Passes	.0003-.0009	.0003-.0026	.0003-.004
TITANIUM	25 Rc	50-130	100-170	.0003-.0004 3 Passes	.0003-.00045 3 Passes	.0003-.001 2 Passes	.0003-.0009	.0003-.0015	.0003-.003
HEAT TREATED ALLOYS (38-45Rc)	40 Rc	50-90	90-150	.0003-.0004 3 Passes	.0003-.00045 3 Passes	.0003-.0005 2 Passes	.0003-.0008	.0003-.001	.0003-.0025
ALUMINUM	100 HB	100-800	100-1200	.0005-.0015	.0005-.002	.0005-.0025	.0005-.003	.0005-.006	.0005-.009
BRASS, ZINC	80 HB	200-350	200-750	.0005-.0015	.0005-.002	.0005-.0025	.0005-.003	.0005-.006	.0005-.009

\*SFM = Surface Feet per Minute

**Parameters are a starting point based on machinability rating at hardness listed. Check machinability rating of the material to be machined and adjust accordingly.**





# THREAD MILL TROUBLESHOOTING

PROBLEM	CAUSE	SOLUTION
TAPERED THREADED HOLE	TOOL PRESSURE	Reduce the chip load and/or make more radial passes.
NO-GO GAGE GOES & GO GAGE DOES NOT GO	THREAD OVERCUTTING	Use a tool of smaller diameter with correct pitch. Make sure helical "ramp in" is used.
TEETH ARE CHIPPING	TOOL PRESSURE	Reduce feed rate per tooth.
	BUILT-UP EDGE	Use a coated tool to help reduce built-up edge.
RAPID WEAR	TOOL RUBBING NOT CUTTING	Increase chip load per tooth.
TEETH ARE BURNING	TOO MUCH HEAT	Reduce speed. Use a coated tool. Increase coolant.
TOOL BREAKS	TOO MUCH TOOL PRESSURE	Helical "arc in" must be used. Reduce feed rate and/or use more radial passes. Adjusted Feed Rate (AFR) must be used. (See Thread Mill Feed and Speed Chart)

Thread milling tools form a thread using a motion referred to as "helical interpolation." This process involves the machine simultaneously moving all three axes. The resulting motions are circular and axial. The "X" and "Y" axes move in a circular manner and the "Z" axis in an axial direction per 360° at a distance equal to the pitch of the thread being machined. The tool should "ramp in" over 90° in order to avoid breakage. This must be a helical move. Move "Z" axially by  $\text{pitch} \div 4$  since  $90^\circ$  is  $360^\circ \div 4$ .

Bottom-to-top climb cutting machining is recommended when machining a right-hand thread. This will avoid re-cutting any chips. For left hand threading, a top-to-bottom machining with a right-hand helical tool is the preferred method. Refer to troubleshooting chart above for solutions to potential thread milling problems.



å ã ç ã ~ ç ã Ä ^ Á , , Ë ^, { æ ç [[ • È { Å Å / Å È € È í í È Ì | Å Å Å Å [[ • Ö } ^, { æ ç [[ • È {